



Your Vision, Our Future

Medical Information Technologies Antivirus and Update Policy

May 2017

Olympus does not install virus protection software, Microsoft® critical updates, or OEM BIOS and driver updates on EndoWorks systems.

Customers may install antivirus software on their EndoWorks systems, but assumes responsibility for support. Olympus has not performed any testing with antivirus applications to determine their impact on EndoWorks. Customers have reported successful installations of McAfee® and Symantec™ (Norton™) antivirus software programs on EndoWorks systems without any reported problems. Please note when configuring an antivirus application, Olympus requires you to exclude the directories and files from the virus scan as indicated in the IT Specification document that is posted on the Olympus EndoWorks website (www.EndoWorks.com).

Olympus will no longer publish approved Windows Updates for EndoWorks. Olympus recommends that you distribute the latest Windows Updates to EndoWorks per your company's security policy. Olympus will no longer perform OEM BIOS and driver update testing. Updates of this nature may be performed at your own risk.

You may contact the Olympus Technical Assistance Center (1-800-848-9024) with any questions or concerns.